

TRADE IN AMOUNT

\$ (2,500⁰⁰)

COST OF ONE WHEEL LOADER

\$ 84,750⁰⁰

LESS TRADE IN AMOUNT

\$ (2,500⁰⁰)

NET COST OF WHEEL LOADER

\$ 82,250⁰⁰

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST

\$ No Bid


GUARANTEED RE-PURCHASE PRICE

\$ No Bid

PERFORMANCE BOND COST

\$ No Bid125 HP FOUR WHEEL DRIVE WHEEL LOADER
Page 3 of 3

VENDOR SIGNATURE

Crescent Machinery Co.
Central Texas Equipment Division
127 E. Riverside Dr.
Austin, Tx 78704

512-442-2371

800-252-5678

DO NOT INCLUDE ANY TAX IN YOUR BID SINCE WILLIAMSON COUNTY IS TAX EXEMPT.

TRADE IN AMOUNT

\$ NB

COST OF ONE PRODUCTION ARTICULATED MOTOR GRADER

\$ No Bid

LESS TRADE IN AMOUNT

\$ No Bid

NET COST OF PROD. ARTICULATED MOTOR GRADER

\$ No Bid

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST

\$ No Bid

GUARANTEED RE-PURCHASE PRICE

\$ No Bid

PERFORMANCE BOND COST

\$ No Bid

PRODUCTION ARTICULATED MOTOR GRADER
Page 4 of 4

VENDOR SIGNATURE


Crescent Machinery Co.
Central Texas Equipment Division
127 E. Riverside Dr.
Austin, Tx 78704

160

WILLIAMSON COUNTY BID FORM

INDUSTRIAL 4 WHEEL DRIVE BACKHOE
 4 WHEEL DRIVE RUBBER TIRED WHEEL LOADER
 ARTICULATED MOTOR GRADER
 SINGLE SMOOTH DRUM VIBRATORY COMPACTOR
 VIBRATORY PAD FOOT COMPACTOR

BID NUMBER: 00WC206 BID OPENING DATE & TIME: NOVEMBER 9, 1999 - 10:30 AM

The undersigned, by his/her signature, represents that he/she is authorized to bind the bidder to fully comply with the terms and conditions of the attached Invitation for Bid, Specifications, and Special Provisions for the amount(s) shown on the accompanying bid sheet(s). By signing below, you have read the entire document and agreed to the terms therein.

NAME OF BIDDER: Holt Company

Mailing Address: P.O. Box 1604

City: Austin State: TX Zip: 78767

Telephone: (512) 282-2011 Fax: (512) 280-1965

Jeff Kell

Signature of Person Authorized to Sign Bid

Date of BID: 11-9-1999

Name and Title of Signer: Jeff Kell, Machine Sales

(Please Print or Type)

PLEASE COMPLETE THE FOLLOWING:

Prompt Payment Discount: _____% _____ days. (If no discount is offered, Net 30 will apply.)

[] "all or none" basis. (Will accept award of "all" items only. If left blank, low item will apply.)

[x] low item basis (Will accept award on "any or all" items.)

List Additional Limitations if applicable: _____

DO NOT SIGN OR SUBMIT THIS FORM
WITHOUT READING ENTIRE DOCUMENT

THIS FORM MUST BE COMPLETED, SIGNED AND RETURNED WITH BID

Page 6 of 8

161

TRADE IN AMOUNT \$ \$4,500.00

COST OF ONE WHEEL LOADER \$ \$91,760.00

LESS TRADE IN AMOUNT \$ \$4500.00


NET COST OF WHEEL LOADER \$ \$ 87,260.00

	3 Yr or 5000 Hr	5 Yr or 7500 Hr
LIFE CYCLE COST BID:		
GUARANTEED REPAIR COST	\$ <u>\$400.00</u>	\$500.00
GUARANTEED RE-PURCHASE PRICE	\$ <u>\$72,755.00</u>	\$56,977.00
PERFORMANCE BOND COST	\$ <u>\$1,517.00</u>	\$1,517.00

10/25/99 10:54 FAX

019

Delivery - 10 weeks ARO



TRADE IN AMOUNT \$ \$8,200.00

COST OF ONE BACKHOE LOADER \$ \$59,408.00

LESS TRADE IN AMOUNT \$ \$8,200.00

NET COST OF BACKHOE LOADER \$ \$51,208.00

ALTERNATE:
CAB A.C. GROUP \$ \$1,625.00

LIFE CYCLE COST BID:	3 Year or 5000 Hr	5 Yr or 7500 Hr
GUARANTEED REPAIR COST	\$ <u>\$400.00</u>	\$500.00
GUARANTEED RE-PURCHASE PRICE	\$ <u>\$37,823.00</u>	\$27,146.00
PERFORMANCE BOND COST	\$ <u>\$891.00</u>	\$891.00

Delivery - 10 weeks ARO

DO NOT INCLUDE ANY TAX IN YOUR BID SINCE WILLIAMSON COUNTY IS TAX EXEMPT.

TRADE IN AMOUNT	\$ <u>\$12,515.00</u>	
COST OF ONE PRODUCTION ARTICULATED MOTOR GRADER	\$ <u>\$127,510.00</u>	
LESS TRADE IN AMOUNT	\$ <u>\$12,515.00</u>	
NET COST OF PROD. ARTICULATED MOTOR GRADER	\$ <u>\$114,995.00</u>	
	3 Year or	5 Year or
	5000 Hours	7500 Hr
LIFE CYCLE COST BID:		
GUARANTEED REPAIR COST	\$ <u>\$400.00</u>	\$500.00
GUARANTEED RE-PURCHASE PRICE	\$ <u>\$103,179.00</u>	\$89,175.00
PERFORMANCE BOND COST	\$ <u>\$1,940.00</u>	\$1940.00

Delivery - 10 weeks ARO

PRODUCTION ARTICULATED MOTOR GRADER
Page 4 of 4

VENDOR SIGNATURE 

164

VOL 0108 PAGE 189

MACHINE SHALL BE EQUIPPED THE FOLLOWING ITEMS:

Dual adjustable cushioned operators seat w/seat belt.

ROPS canopy w/vibration isolation system

A vehicle-warning package for charge system, brake engine oil and temperature, backup alarm, horn, fuel gauge, hour meter and vibratory tachometer.

Vandalism protection group, for dash and engine.

LITERATURE:

One set of operators, parts book, and service manual (manual shall include disassembly assembly and trouble shooting information for both the machine and engine).

WARRANTY:

Successful bidder shall provide through dealer and or manufacturer one (1) full year of warranty on parts and labor including travel time and mileage.

DESTINATION:

Unit shall be delivered to Williamson County Central Maintenance Facility, 3151 S.E. InnerLoop, Georgetown, Texas. Unit shall be complete, all fluid levels correct and ready for work.

NOTICE TO BIDDERS:

Please include in your bid a complete and detailed specification on the unit proposed and delivery date.

THE COUNTY IS TAX EXEMPT SO DO NOT INCLUDE TAX IN YOUR BID.

signature, backup alarm

COST OF ONE PADFOOT VIBRATORY SOIL COMPACTOR**\$ \$109,551.00****LIFE CYCLE COST BID:****3 Yr or 5000 Hr**

or a disassembly ass.

5 yr/7500 Hr**GUARANTEED REPAIR COST****\$ \$400.00****\$500.00****GUARANTEED RE-PURCHASE PRICE****\$ \$79,123.00****\$57,028.00****PERFORMANCE BOND COST****\$ \$1,714.00****\$1,714.00****Delivery - 8 weeks AR**

by 3151 S E InnerLoop

ready for work.


unit proposed and de

C BID

RECORDERS MEMORANDUM
 All or parts of the text on this page was not
 clearly legible for satisfactory recordation

PADFOOT VIBRATORY SOIL COMPACTOR
 Page 2 of 2

VENDOR SIGNATURE

S. _____


165

VOL 0108 PAGE 190

MACHINE SHALL BE EQUIPPED THE FOLLOWING ITEMS:

Dual adjustable cushioned operators seat w/seat belt.

ROPS canopy w/vibration isolation system

A vehicle warning package for charge system, brake engine oil and temperature, backup alarm, horn, fuel gauge, hour meter and vibratory tachometer.

Vandalism protection group, for dash and engine.

LITERATURE:

One set of operators, parts book, and service manual (manual shall include disassembly assembly and trouble shooting information).

WARRANTY:

Successful bidder shall provide through dealer and or manufacturer one (1) full year of warranty on parts and labor including travel time and mileage.

TRADE IN:

Unit #2405 a 1980 Ferguson 8-12 ton static steel wheel Roller w/Detroit Diesel power.

TO MAKE AN APPOINTMENT TO SEE TRADE IN CONTACT MIKE FOX AT THE WILLIAMSON COUNTY CENTRAL MAINTENANCE FACILITY, PHONE (512) 930 3349.

DESTINATION:

Unit shall be delivered to the Williamson County Central Maintenance Facility, 3151 S.E. Innerloop, Georgetown Texas. All service levels correct and ready for work. Trade in may be picked up at time of delivery.

NOTICE TO BIDDERS:

Please include in your bid a complete and detailed specification on the unit proposed and delivery date.

THE COUNTY IS TAX EXEMPT SO DO NOT INCLUDE TAX IN YOUR BID. (seller bid)

TRADE IN AMOUNT	\$ <u>\$1,800.00</u>
	1 full year of warranty
COST OF ONE VIBRATORY SMOOTH DRUM SOIL COMPACTOR	\$ <u>\$97,795.00</u>
LESS TRADE IN AMOUNT	\$ <u>\$1,800.00</u>
NET COST OF VIB. SMOOTH DRUM SOIL COMPACTOR	\$ <u>\$95,995.00</u>

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST

3 Yr or 5000 Hr	5 Yr or 7500 Hr
\$ <u>\$400.00</u>	\$ <u>\$500.00</u>

GUARANTEED RE-PURCHASE PRICE

\$ <u>\$71,825.00</u>	\$ <u>\$49,751.00</u>
-----------------------	-----------------------

PERFORMANCE BOND COST

\$ <u>\$1,524.00</u>	\$ <u>\$1,524.00</u>
----------------------	----------------------

VIBRATORY SMOOTH DRUM SOIL COMPACTOR

VENDOR SIGNATURE

Page 2 of 2

Delivery - 8 weeks ARO

OCT 25 1999 21:01

PAGE 25

166

DO NOT INCLUDE ANY TAX IN YOUR BID SINCE WILLIAMSON COUNTY IS TAX EXEMPT.

TRADE IN AMOUNT \$ 6000⁰⁰

COST OF ONE PRODUCTION ARTICULATED MOTOR GRADER ^{H.A.C. PRICE *} \$ 119988⁰⁰

LESS TRADE IN AMOUNT \$ 6000⁰⁰

NET COST OF PROD. ARTICULATED MOTOR GRADER \$ 113988⁰⁰

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST \$ SEE WARRANTY

GUARANTEED RE-PURCHASE PRICE \$ NO BID

PERFORMANCE BOND COST \$ N.A.

* includes 1.65% H.B.A.C. FEE



8000 Blue Goose Road
Manor, TX 78653
Pager (512) 495-1997
Home (512) 376-4330
<http://www.rdoequipment.com>



TIM L. SCHUELKE
Territory Manager

Office (512) 272-4141
Toll Free (800) 775-3838
FAX (512) 272-9365
Mobile (512) 217-5224

PRODUCTION ARTICULATED MOTOR GRADER
Page 4 of 4

VENDOR SIGNATURE

Tim Schuelke
RDO

VOL 0108 PAGE 192

TRADE IN AMOUNT

\$ 3000⁰⁰

COST OF ONE WHEEL LOADER

H.G.A.C. PRICE \$:

\$ 86011⁰⁰ includes 1.65% FEE

LESS TRADE IN AMOUNT

\$ 3000⁰⁰

NET COST OF WHEEL LOADER

\$ 83011⁰⁰

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST

\$ SEE ATTACHED WARRANTY

GUARANTEED RE-PURCHASE PRICE

\$ NO BID

PERFORMANCE BOND COST

\$ N.A.

8000 Blue Goose Road
 Manor, TX 78653
 Pager (512) 495-1997
 Home (512) 376-4330
<http://www.rdoequipment.com>



TIM L. SCHUELKE

Territory Manager

Office (512) 272-4141
 Toll Free (800) 775-3838
 FAX (512) 272-9365
 Mobile (512) 217-5224

125 HP FOUR WHEEL DRIVE WHEEL LOADER
 Page 3 of 3

VENDOR SIGNATURE

Tim Schuelke
 RDO

TRADE IN AMOUNT

\$ \$6000.00

COST OF ONE BACKHOE LOADER

\$ 54393.00

LESS TRADE IN AMOUNT

\$ \$6000.00

NET COST OF BACKHOE LOADER

\$ \$48393.00

ALTERNATE:

CAB A.C. GROUP

\$ \$1272

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST

\$ SEE WARRANTY

GUARANTEED RE-PURCHASE PRICE

\$ NO B.D

PERFORMANCE BOND COST

\$ N.A.

8000 Blue Goose Road
 Manor, TX 78653
 Pager (512) 495-1997
 Home (512) 376-4330
<http://www.rdoequipment.com>

**TIM L. SCHUELKE**

Territory Manager

Office (512) 272-4141
 Toll Free (800) 775-3838
 FAX (512) 272-9365
 Mobile (512) 217-5224

Tim L. Schuelke
 BDO

WILLIAMSON COUNTY BID FORM

VOL 0108 PAGE 194

INDUSTRIAL 4 WHEEL DRIVE BACKHOE
4 WHEEL DRIVE RUBBER TIRED WHEEL LOADER
ARTICULATED MOTOR GRADER
SINGLE SMOOTH DRUM VIBRATORY COMPACTOR
VIBRATORY PAD FOOT COMPACTOR

BID NUMBER: 00WC206 BID OPENING DATE & TIME: NOVEMBER 9, 1999 - 10:30 AM

The undersigned, by his/her signature, represents that he/she is authorized to bind the bidder to fully comply with the terms and conditions of the attached Invitation for Bid, Specifications, and Special Provisions for the amount(s) shown on the accompanying bid sheet(s). By signing below, you have read the entire document and agreed to the terms therein.

NAME OF BIDDER:

Texava Machinery

Mailing Address:

12805 Highway 290 East

City: Manor

State: TX

Zip: 78653

Telephone:

(512) 272-8922

Fax:

(512) 272-4012



Signature of Person Authorized to Sign Bid

Date of BID: Nov 9, 99

Name and Title of Signer:

Bud De Groot

Branch Mgr.

(Please Print or Type)

PLEASE COMPLETE THE FOLLOWING:

Prompt Payment Discount. _____% _____days. (If no discount is offered, Net 30 will apply.)

[] "all or none" basis. (Will accept award of "all" items only. If left blank, low item will apply.)

[x] low item basis. (Will accept award on "any or all" items.)

List Additional Limitations if applicable: _____

DO NOT SIGN OR SUBMIT THIS FORM
WITHOUT READING ENTIRE DOCUMENT

THIS FORM MUST BE COMPLETED, SIGNED AND RETURNED WITH BID

580LAs Alternate 73hp

VOL 0108 PAGE 195

TRADE IN AMOUNT,

\$ 6,500.00

COST OF ONE BACKHOE LOADER

\$ 52,135.00

LESS TRADE IN AMOUNT

\$ 6,500.00

NET COST OF BACKHOE LOADER

\$ 45,635.00

ALTERNATE:

CAB A.C. GROUP

\$ 1,315.00

LIFE CYCLE COST BID:

GUARANTEED REPAIR COST

\$ 3,750.0012,250.00

GUARANTEED RE-PURCHASE PRICE

\$ 22,818.0017,798.00

PERFORMANCE BOND COST

\$ 137.00108.00580 L Turbo

Trade In Amount

6,500.00

Cost of one Loader Backhoe

53,912.00

Less Trade In Amount

6,500.00

Net Cost of Backhoe Loader

47,412.00

Alternate

Cub A.C. Group

1,315.00

Life Cycle Cost Bid:

Guaranteed Repair Cost

3,750.0012,250.00

Guaranteed Re-Purchase Cost

24,364.0019,000.00

Performance Bond Cost

147.00114.00

VOL 0108 PAGE 196

TRADE IN AMOUNT \$ 2,500.⁰⁰

COST OF ONE WHEEL LOADER \$ 81,715.⁰⁰

LESS TRADE IN AMOUNT \$ 2,500.⁰⁰

NET COST OF WHEEL LOADER \$ 79,215.⁰⁰

LIFE CYCLE COST BID:	3yr	5yr.
GUARANTEED REPAIR COST	\$ <u>3,598.⁰⁰</u>	<u>10,962.⁰⁰</u>
GUARANTEED RE-PURCHASE PRICE	\$ <u>39,608.⁰⁰</u>	<u>30,900.⁰⁰</u>
PERFORMANCE BOND COST	\$ <u>240.⁰⁰</u>	<u>186.⁰⁰</u>

VOL 0108 PAGE 197

MACHINE SHALL BE EQUIPPED THE FOLLOWING ITEMS:

Dual adjustable cushioned operators seat w/seat belt.

ROPS canopy w/vibration isolation system

A vehicle warning package for charge system, brake engine oil and temperature, backup alarm, horn, fuel gauge, hour meter and vibratory tachometer

No TACH,

Vandalism protection group, for dash and engine.

LITERATURE:

One set of operators, parts book, and service manual (manual shall include disassembly assembly and trouble shooting information).

WARRANTY:

Successful bidder shall provide through dealer and or manufacturer one (1) full year of warranty on parts and labor including travel time and mileage.

TRADE IN:

Unit #2405 a 1980 Ferguson 8-12 ton static steel wheel Roller w/Detroit Diesel power.

TO MAKE AN APPOINTMENT TO SEE TRADE IN CONTACT MIKE FOX AT THE WILLIAMSON COUNTY CENTRAL MAINTENANCE FACILITY, PHONE (512) 930 3349.

DESTINATION:

Unit shall be delivered to the Williamson County Central Maintenance Facility, 3151 S.E. Innerloop, Georgetown Texas. All service levels correct and ready for work. Trade in may be picked up at time of delivery

NOTICE TO BIDDERS:

Please include in your bid a complete and detailed specification on the unit proposed and delivery date.


THE COUNTY IS TAX EXEMPT SO DO NOT INCLUDE TAX IN YOUR BID.

TRADE IN AMOUNT\$ 1,000.00**COST OF ONE VIBRATORY SMOOTH DRUM SOIL COMPACTOR**\$ 78,000.00**LESS TRADE IN AMOUNT**\$ 1,000.00**NET COST OF VIB. SMOOTH DRUM SOIL COMPACTOR**\$ 77,000.00**LIFE CYCLE COST BID:****GUARANTEED REPAIR COST**

	3yr	5yr
GUARANTEED REPAIR COST	\$ <u>4,544.00</u>	<u>13,700.00</u>
GUARANTEED RE-PURCHASE PRICE	\$ <u>37,300.00</u>	<u>28,350.00</u>
PERFORMANCE BOND COST	\$ <u>224.00</u>	<u>174.00</u>

GUARANTEED RE-PURCHASE PRICE**PERFORMANCE BOND COST**VIBRATORY SMOOTH DRUM SOIL COMPACTOR
Page 2 of 2

VENDOR SIGNATURE



VOL 0108 PAGE 198

MACHINE SHALL BE EQUIPPED THE FOLLOWING ITEMS:

Dual adjustable cushioned operators seat w/seat belt.

ROPS canopy w/vibration isolation system

A vehicle-warning package for charge system, brake engine oil and temperature, backup alarm, horn, fuel gauge, hour meter and vibratory tachometer.

No Tachometer

Vandalism protection group, for dash and engine.

LITERATURE:

One set of operators, parts book, and service manual (manual shall include disassembly assembly and trouble shooting information for both the machine and engine)

WARRANTY:

Successful bidder shall provide through dealer and or manufacturer one (1) full year of warranty on parts and labor including travel time and mileage.

DESTINATION:

Unit shall be delivered to Williamson County Central Maintenance Facility, 3151 S.E. InnerLoop, Georgetown, Texas. Unit shall be complete, all fluid levels correct and ready for work.

NOTICE TO BIDDERS:

Please include in your bid a complete and detailed specification on the unit proposed and delivery date.

THE COUNTY IS TAX EXEMPT SO DO NOT INCLUDE TAX IN YOUR BID.**COST OF ONE PADFOOT VIBRATORY SOIL COMPACTOR**\$ 80,500.00**LIFE CYCLE COST BID:****GUARANTEED REPAIR COST**\$ 4,544.0013,700.00**GUARANTEED RE-PURCHASE PRICE**\$ 38,900.0029,600.00**PERFORMANCE BOND COST**\$ 234.00180.00

AGENDA ITEM # 19

Discuss and take appropriate action on change order for Farmers State Bank..

Architect David Voelter did not have a change order but brought the court up to date on the building construction. One \$5,500.00 change order for change in duct work and \$10,770.00 change order to rebuild existing trusses for total of \$118,535.00.

Mr. Voelter discussed the possibility of extending elevator shaft to accommodate the building directly south of the old Farmers State Bank building. The owner is interested in participating in the elevator and the current contractor has suggested an additional \$7,000.00 to construct the shaft to accommodate both buildings - an 8'x8' space extended 6'.

Numerous research efforts have been exerted to determine the ownership of the property behind the Farmers State Bank building where the elevator shaft will be constructed. The survey plat which was filed in the County Clerk's office at one time is no longer of record. The deed conveying the building to Williamson County does not contain a metes and bounds description.

Judge Doerfler and Commissioner Hays have met with the owner of the building located directly south of the old Farmers State Bank building who is interested in having an elevator installed to accommodate both buildings. However the owner is hesitant to commit to payment of the additional funds required for shaft modification to accommodate her building. She also

thinks she owns all the alley behind both buildings.

County Attorney Gene Taylor requested copies of prior title research from Mr. Voelter.

Mr. Voelter advised the façade cleaning should be finished soon and pigeon treatment will be accomplished.

No action was taken on this item.

AGENDA ITEM # 20

*

Consider approving intergovernmental agreement with City of Taylor for construction of road at the Taylor Airport.

Commissioner Limmer advised the City of Taylor has paid approximately \$1,044,723.00 to date for Taylor Airport expansion. Since County Road 398 will require re-routing to the north the city is requesting the county also accept responsibility of southern expansion of County Road 398. This is phase one according to plans by Turner Collie and Braden Engineering with cost estimate of approximately \$700,000.00. This phase does not include installation of water lines or bridge.

Commissioner Boatright requested the County Attorney review the proposed intergovernmental agreement before any signatures are affixed. Also he felt if Williamson County contributes the funds the City of Taylor shall be responsible for all material, equipment, labor, fuel, engineering, supervision and any and all other expenses and responsibilities involved in the road construction.

First Assistant County Attorney Dale Rye suggested the agreement state that all right, title and interest of Williamson County in the remaining east end of County Road 398 off FM 397 be abandoned to the City of Taylor.

Also discussed was the \$700,000.00 be paid from cash ending balance with reimbursement from possible future issuance of \$20m Certificates of Obligation.

Moved: Commissioner Hays

Seconded: Commissioner Boatright

Motion: To approve interlocal agreement with the City of Taylor who accepts full responsibility for all necessary arrangements regarding County Road 398 after Williamson County contributes up to \$700,000.00 and dedicates the short eastern end of County Road 398 off FM 397 to City of Taylor contingent upon review by Williamson County Attorney.

Commissioner Boatright withdrew his second to the motion.

Motion failed for lack of second.

No action was taken on this item which will be added to the agenda of November 16, 1999.

AGENDA ITEM # 21

Discuss and take appropriate action on damage claim from Michael Freeman.

First Assistant County Attorney Dale Rye explained the damage and verification of same and recommended payment to Mr. Freeman.

Moved: Commissioner Hays

Seconded: Commissioner Limmer

Motion: To approve payment of \$75.00 county mower damages to pick up side window of Michael Freeman.

Vote: Motion carried 5 - 0

< Clerk copy here >

Texasdelphia

Michael Freeman
General Manager

HONG
990-7568

2000 IH 35 South
Round Rock, TX 78681

PH 512-238-9955
FAX 512-238-9944

PHONE CALL									
FOR	DATE 8/11 TIME 12:00 PM								
M	Michael Freeman								
OF									
PHONE	<input type="checkbox"/> FAX	<input type="checkbox"/> MOBILE	238-9955						
MESSAGE	AREA CODE	NUMBER	EXTENSION						
Sharon Deborah									
Leifest -									
Michael Freeman									
- release -									
SIGNED	<table border="1"> <tr><td>PHONED</td></tr> <tr><td>RETURNED YOUR CALL</td></tr> <tr><td>PLEASE CALL</td></tr> <tr><td>WILL CALL AGAIN</td></tr> <tr><td>CAME TO SEE YOU</td></tr> <tr><td>WANTS TO SEE YOU</td></tr> </table>			PHONED	RETURNED YOUR CALL	PLEASE CALL	WILL CALL AGAIN	CAME TO SEE YOU	WANTS TO SEE YOU
PHONED									
RETURNED YOUR CALL									
PLEASE CALL									
WILL CALL AGAIN									
CAME TO SEE YOU									
WANTS TO SEE YOU									

FORM 4003

approved 11-9-99
John C. Daefler

pay 75.00

[Signature]

RECORDERS MEMORANDUM
All or parts of the text on this page was not clearly legible for satisfactory recordation.



Peggy,

We need to have this set
on the ~~Commissioner's~~ Court Agenda.

Need to pay \$75.

Thanks
D



RECORDERS MEMORANDUM
All or parts of the text on this page was not
clearly legible for satisfactory recordation.

SHARON C. BENEDICT
Administrative Assistant



1900 Georgetown Inner Loop, Ste. B
Georgetown, Texas 78626
Telephone (512) 930-3330
Fax (512) 930-3335

Williamson County
Unified Road System

M E M O

TO: Dan Gattis, County Attorney
FROM: Sharon C. Benedict
DATE: June 11, 1999
SUBJECT: Vehicle damage claim -Michael Freeman

This man went ahead and had his truck window repaired and brought a receipt for that repair and the tint job. It looks as though he turned it in to his insurance company because the receipt shows a \$50.00 deductible.

Do we reimburse an individual beyond their deductible(out of pocket expense) if their insurance covers the damage, providing it is determined that we caused the damage.

Please let me know, I haven't run into this before.

Thanks,

Sharon

\$75

received

6-8-99

6/7/99

To whom This may Concern,

On Monday June 7th 1999
 I was traveling northbound
 on the Pflugerville loop (CR 170)
 on my way to work. Approximately
 9:10 A.M. I noted a Highway crew
 in front of me and slowing traffic
 AS I got closer I realized it
 was a lawn tractor & a caution
 vehicle. AS I waited for the
 oncoming traffic to clear, I
 proceeded around the tractor &
 caution vehicle AS did the cars
 before me. AS I was passing
 the mower section I heard
 a loud Pop. I looked immediately
 at the area of the noise & saw
 my passenger window shattered
 but still intact. I pulled over
 immediately. when stopped I noted
 the window still cracking like
 a Domino effect. Thinking how
 lucky I was that window was not down
 AS it sometimes is, I collected myself
 for a minute. I then exited my
 truck and approached the tractor
 & caution vehicle. →

RECORDERS MEMORANDUM
 All or parts of the text on this page was not
 clearly legible for satisfactory recordation.

RECORDERS MEMORANDUM

All or parts of the text on this page was not
clearly legible for satisfactory recordation.

PAGE
10

The two men Both approached me. The First Gentleman asked How he could help me. I showed him my window & began to apologize Repeatedly & went to call his Foreman to Discuss the problem

The Second Gentleman began to tell How many safety type issues they Deal with on a Daily Basis and how they have warned their Supervisor of these type issues and there Rate of occurrence.

In short Both men admitted Responsibility, concurred that they would be upset as well and gave me their names, Foremans name, Tractor ID # and Contact phone numbers. They also Apologized again and wished for A speedy Resolution.

Sincerely,

Michael J. _____

received
6-10-99

VOL 0108 PAGE 206

6-7-99

10:15 AM

S.G. BENGSTON WAS MOWING ON
CO. RD. 172. IT WAS IN THE
SPRAY TRUCK WITH MY HAZARD'S
LIGHTS ON ~~and~~ ABOUT 50 FT
BEHIND HIM. I SEEN A BLUE
GMC PICK UP PASS BY US
AND THEN HE PULLED OVER
IN FRONT OF THE MOWER.
THAT'S WHEN HE CALLED US
TO HIS TRUCK AND SAID A
ROCK SHATTERED HIS RIGHT
SIDE WINDOW WHEN HE PASSED
THE MOWER. THAT'S ALL I SEEN

Sonny Burkalew

RECORDERS MEMORANDUM
All or parts of the text on this page was not
clearly legible for satisfactory recordation.

4-7-99

S.L. Roughton

VOL 0108 PAGE 207

received
4-8-99

RECORDERS MEMORANDUM

All or parts of the text on this page was not
clearly legible for satisfactory recordation.

While mowing Co Rd 170 I was

going North cutting the East ditch on Tractor #282
at 9:10AM with Sonny Buckalar following behind
me in the Spray truck with Sign Board with
flashing Yellow Bar on it to warn traffic behind
me. A blue 1997 Chev. Pickup came on around
me and pulled past me & then pulled to the side & stopped.
The driver got out & went to the passengers side & looked
and then started walking towards me. I stopped
the Tractor & met him. He said that when he
came around me his passenger window popped &
cracked all over. Sonny Buckalar & I looked at
the window & it had a fresh nick on it & the
glass was still cracking. We moved off the road
to a safe location & I took his name & Veh
info. He wanted his window fixed & I told him I
would call my Foreman & report the incident. Jesse Hamer
adv. me to have him call the Main office in Georgetown &
get instructions on what steps he needed to take.

1997 GMC P.U. Blue Texlic 226-387

Michael FREEMAN Home PS# 990-7368

17304 Bush Mill Rd. Work 238-9955

183

Pflugerville, TEXAS.

Note: I did NOT Hear or see ANY Rock strike his window but
DAMAGE WAS EVIDENT



2112 Rutland Drive, Suite 179
Austin, Texas 78758

835-7575

FED ID# 456-04-7739

SAFELITE GLASS CORP.
PO BOX 182277
ATTN:AIC BILLING
COLUMBUS, OHIO 43218-2277

INV #	32946A	DATE	06/08/1999
CUST. #	SGC	SALE TYPE	SA
CUST. P.O.		SOLD BY	SA
FED. TAX #		INSTL BY	BM

MICHEAL FREEMAN
2000 IH 35 SOUTH
ROUND ROCK, TX

800-890-1276 Fax 800-567-5568

Hm512-238-9955 Wk - -

YEAR	1997	MAKE	GMC	POLICY		
MODEL	C SERIES PICKUP	BODY STYLE	2 DOOR EXTENDED CA	AUTHORIZED BY	FAX	
LC		V.I.N.	EGDEC19R6V1560455	CLAIM CODE	333327	
				LOSS DATE	06/07/1999	
PHONE	512-238-9955	BUS. PHONE	- -	DAMAGE/CAUSE		
QTY	PART	DESCRIPTION	BLOCK SIZE	LIST	PRICE	TOTAL

***** D U P L I C A T E *****

1	DD08305GTYN Door (Front) (Right) (slr cont 25x35.8	335.60	162.77	162.77
	Labor (1.50 hours)		37.50	

RECORDERS MEMORANDUM
All or parts of the text on this page was not
clearly legible for satisfactory recordation.

TOTAL LABOR (NON-TAXABLE) 37.50

SPECIAL INSTRUCTIONS				SUBTOTAL
<p>All material sold on this invoice is guaranteed to be as specified, and is not safety glazed material unless so marked. It is sold with the understanding that this material will not be glazed in a "hazardous location" as defined by the Consumer Product Safety Commission.</p> <p>All merchandise returned for credit, refund or exchange must be in resalable condition, authorized for return, accompanied by this receipt, and may be subject to restocking fee. No returns will be authorized for special orders or cut flat glass. Terms of payment are 30 days from invoice date. A service charge of 0.0 % per month (0.0 % annum) will be added to past due accounts.</p>				184
				TOTAL DEDUCT. 200.27
				BALANCE -50.00
				150.27

RECEIVED BY:

The glass listed has been replaced / repaired with like kind and quality to my entire satisfaction, and

AUSTIN

CAR PROTECTION & MORE

Auto Tint & Alarm
Residential & Commercial Solar Film
15533 IH 35 North
PFLUGERVILLE, TX
990-0303

SOLD BY		DATE	
NAME Michael FREEMAN			
ADDRESS 17304 Bushmills Rd		PHONE 990-7368	
CITY Pflugerville TX 78660			
RECEIVED			
QTY.	DESCRIPTION	PRICE	AMOUNT
1			25 00
2			
3	ONE WINDOW		
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
RECEIVED BY		TOTAL	25 00

3439

NEBS To Reorder Call
1-800-225-6380

THANK YOU

RECORDERS MEMORANDUM
All or parts of the text on this page was not
clearly legible for satisfactory recordation.

AGENDA ITEM # 22

*

Discuss and take appropriate action on damage claim from L.V. and Lois Reese.

First Assistant County Attorney Dale Rye explained the fallen limb hood damage and verification of same and recommended payment to L.V. and Lois Reese.

Moved: Commissioner Hays

Seconded: Commissioner Limmer

Motion: To approve payment of \$1,005.00 for fallen limb damages to automobile hood of L.V. and Lois Reese.

Vote: Motion carried 5 - 0

< Clerk copy here >

LEE H. GARRETT
SAFETY COORDINATOR



3151 S.E. Inner Loop, Suite B
Georgetown, Texas 78626
Telephone (512) 930-3330
Fax (512) 930-3335

Williamson County
Unified Road System

October 21, 1999

MEMO TO: Dan Gattis, County Attorney's Department

SUBJECT: Damage caused by Unified Road System Employee

Attached are two witness statements from Unified Road System employees, along with Polaroid photos of damage claimed to be caused by a limb falling off a trailer the employees were hauling. Also attached is a statement from the claimant and three estimates of repair damage

The claimed incident occurred on October 19, 1999 at approximately 12:30 pm. I took the photos of the claimant's vehicle. The claimant showed me the alleged damage, which was two paint chips on the front left side of the vehicle hood, and scratches to the lower valence panel. I am turning this claim over to your office as instructed by Sharon Benedict. Please let me know if you have any questions.

Sincerely,

Lee H. Garrett

approved 11-9-99 1005.00
John G. Daifler
VED FOR PAYMENT

Authorized Signature

Cc: Greg Bergeron

Budget Line Item

Amount

186



RECORDERS MEMORANDUM
All or parts of the text on this page was not
clearly legible for satisfactory recordation.



on this date 10-19-99

Ricardo & Chris were hauling Brush on a trailer when a limo felt up and landed on the Road and a 1987 Pontiac Grand Am Ran over and scrunched the hood.

It happen on the service Road
Between Williams Dr. and State Road 29
we had a chain over it
this happen about 12:30 P.M.

Ricardo Salas

received

10-20-99

10-19-99

We were coming of Williams Dr.
 onto the Service rd. we got on
 the Bridge it was a Tree Branch
 that blew off the Trailer in the road.
 We Couldn't Stop because Car was
 behind us and on the side we
 Couldn't Stop at the time we hit
 the Branch. It's Caught under the
 Car. one of the Worker Come. And
 gotten it from under the Car.
 The time was About. Between 12:15
 and 1.0 Clock.

RECEIVED

NOV 08 1999

AUDITORS OFFICE
 Williamson County, Texas

Make **the CONNECTION**
 OFFICE COMMUNICATIONS SYSTEMS

NEED TO

PAY.

\$1005.00

OFFICES THROUGHOUT TEXAS
 800-292-1151

Signed
 L. V. Leese
 Wife Lois Leese

189

Date: 10/20/99 01:35 PM
 Estimate ID: 1230
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

BILL'S BODY SHOP, INC.

710 W. UNIVERSITY AVE. GEORGETOWN, TX 78626
 (512) 863-0868
 Fax: (512) 863-3292

Damage Assessed By: LUCKY COPELAND

Deductible: UNKNOWN

Insured: L. V. REESE
 Address: 1820 HART ST. GEORGETOWN, TX 78626
 Telephone: Home Phone(512) 863-5866

Mitchell Service. 917486

Description: 1987 Pontiac Grand Am
 Body Style: 2D Cpe
 VIN: 1G2NE14L1HC872980

Drive Train: 3.0L Inj 6 Cyl AT
 License: RRF17D TX

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	700860	BDY	REPAIR	FRT BUMPER COVER	Existing		2 0*
2	AUTO	REF	REFINISH	FRT BUMPER COVER			C 2.3
3	702220	BDY	REMOVE/REPLACE	GRILLE	10037255 GM PART	72.75	0.2 #
4	711930	BDY	REPAIR	HOOD PANEL	Existing		2.5*
5	AUTO	REF	REFINISH	HOOD OUTSIDE			C 2.9
6	712350	REF	BLEND	R FENDER OUTSIDE			C 1.0
7	712510	BDY	REPAIR	L FENDER PANEL	Existing		1.0* #
8	AUTO	REF	REFINISH	L FENDER OUTSIDE			C 2.0
9	725070	REF	BLEND	L FRT DOOR OUTSIDE			C 1.0
10	732990	BDY	REPAIR	L QUARTER OUTER PANEL	Existing		1.0* #
11	AUTO	REF	REFINISH	L QUARTER PANEL OUTSIDE			C 2.3
12	AUTO	REF	ADD'L OPR	CLEAR COAT			2.8
13	AUTO		ADD'L COST	PAINT/MATERIALS		314.60 *	
14	AUTO		ADD'L COST	HAZARDOUS WASTE DISPOSAL		5.00 *	

* - Judgement Item

- Labor Note Applies

C - Included in Clear Coat Calc

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	8.7	32.00	0.00	0.00	214.40	Taxable Parts	72.75
Refinish	14.3	32.00	0.00	0.00	457.60	Sales Tax @ 7.250%	5.27
Non-Taxable Labor					672.00	Total Replacement Parts Amount	78.02
Labor Summary	21.0				672.00		

ESTIMATE RECALL NUMBER. 10/20/99 13:34:54 1230

Mitchell Data Version: SEP_99_A

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 1999 Mitchell International
 All Rights Reserved

Date: 10/20/99 01:35 PM
 Estimate ID: 1230
 Estimate Version: 0
 Preliminary
 Profile ID: Mitchell

III. Additional Costs				Amount	IV. Adjustments		Amount
Taxable Costs				319.60	Customer Responsibility		0.00
Sales Tax @ 7.250%				23.17			
Total Additional Costs				342.77			
					I. Total Labor:		672.00
					II. Total Replacement Parts:		78.02
					III. Total Additional Costs:		342.77
					Gross Total:		1,092.79
					IV. Total Adjustments:		0.00
					Net Total:		1,092.79

This is a preliminary estimate.

Additional changes to the estimate may be required for the actual repair.

BILL'S BODY SHOP PROVIDES A 1 YR. WARRANTY ON PARTS AND REPAIRS INSTALLED BY THE SHOP PERTAINING DIRECTLY TO COLLISION DAMAGE EXCLUDING SUSPENSION, A/C, OR OTHER ELECTRICAL ASSEMBLY OR COMPONENTS. THE SHOP WILL REPAIR OR REPLACE ANY DEFECTIVE PART WARRANTED, UNLESS CAUSED BY OR DAMAGED RESULTING FROM UNREASONABLE USE OR CARE OF THE VEHICLE. WE OFFER A LIFETIME PAINT WARRANTY. THANK YOU FOR GETTING YOUR ESTIMATE AT BILL'S BODY SHOP, INC. WE LOOK FORWARD TO GIVING YOU A QUALITY REPAIR JOB. HAVE A NICE DAY!

ESTIMATE RECALL NUMBER: 10/20/99 13:34:54 1230

Mitchell Data Version:

SEP_99_A

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994 - 1999 Mitchell International
 All Rights Reserved

Page 2 of 2

ESTIMATE OF REPAIRS

NAME**ADDRESS.**

DATE _____

PHONE

YEAR - MODEL - COLOR	MAKE OF CARE	BODY TYPE	LICENSE NO.	SERIAL NO.	MILEAGE
1987 Chevrolet	Pont	2 Dr	PRF417D	1G2NF141H672986	

[illegible]

THIS ESTIMATE IS BASED ON OUR INSPECTION AND DOES NOT COVER ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE WORK HAS BEEN STARTED. AFTER THE WORK HAS STARTED, WORN OR DAMAGED PARTS WHICH ARE NOT EVIDENT ON FIRST INSPECTION MAY BE DISCOVERED, NATURALLY THIS ESTIMATE CANNOT COVER SUCH CONTINGENCIES. PARTS PRICES SUBJECT TO CHANGE WITHOUT NOTICE. THIS ESTIMATE IS FOR IMMEDIATE ACCEPTANCE.

Estimate made by _____

Estimate Charge **\$**_____

Refund on Repairs \$ _____

Labor 768.00 Hrs. @ 32.00 \$ 768.00

Parts \$ _____ **Less %** _____ **\$** _____

Sublet and Net Items Material..... \$ 237.00

Tax 1.92 % on \$ \$

TOTAL \$1005.00

DAVID COLLISION REPAIR, INC.
900 WEST STREET
GEORGETOWN, TX 78626
PHONE: 512 863 6570
FAX: 512 869 0730

VOL 0108 PAGE 217

CD LOG NO 894-1 DATE 10/20/99

SHOP: DAVID COLLISION REPAIR INC INSP DATE: 10/20/99
ADDRESS: 900 WEST STREET CONTACT: LARRY DAVID
CITY STATE: GEORGETOWN, TX PHONE 1: (512) 863-6570
ZIP: 78626 FAX: (512) 869-0730

OWNER: REESE, L V. HOME PHONE: (512) 863-5866
ADDRESS: 1820 HART STREET
CITY STATE: GEORGETOWN, TX
ZIP: 78626-

POINT OF IMPACT: 4

TYPE OF LOSS: /DRV

LIC#: RRF 17D STATE: TX VIN: UNREADABLE VIN
BODY COLOR: BROWN MILEAGE:
CONDITION: FAIR ACCTNG CTL#:

PROD.DATE: 04/87

PAINT CODE:

*=USER-ENTERED VALUE E=NEW PART EC=ECONOMY PART
EU=SALVAGE PART EP=SEE PX REPORT ET=LABOR PARTIAL REPLACE
IT=LABOR PARTIAL REPAIR I=REPAIR/ALIGN/SUBLET L=REFINISH
N=ADDNL LABOR OPERATION P=CHECK TE=PART/PARTIAL REPLACE
AA=APPEARANCE ALLOWANCE RP=RELATED PRIOR DAMAGE UP=UNRELATED PRIOR DAMAGE
RI=R&I ASSEMBLY

PRELIMINARY ESTIMATE-DO NOT PAY

1987 PONTIAC GRAND AM LE 2DOORS COUPE W3302A/C OPTNS C/24

OPTIONS: TWO-STAGE - EXTERIOR SURFACES TWO-STAGE - INTERIOR SURFACES

OP	GDE	MC	DESCRIPTION	MFG.PART NO.	PRICE	AJ%	HOURS	R
N	0014		FRONT BUMPER COVER R&I	ADDNL LABOR OPERA			1.8	1
I	0014		COVER, FRONT BUMPER	REPAIR			1.5*	1
L	0014	09	COVER, FRONT BUMPER	REFINISH			3.6	4
RI	0067		LAMP, SIDE MARKER	LT R&I ASSEMBLY			0.3	1
RI	0068		LAMP, SIDE MARKER	RT R&I ASSEMBLY			0.3	1
I	0083		PANEL, HOOD	REPAIR			2.0*	1
			REPAIR SCRATCHES					
L	0083		PANEL, HOOD	REFINISH			3.6	4
I	0103		FENDER, FRONT	LT REPAIR			0.5*	1
			REPAIR SCRATCHES					
L	0103		FENDER, FRONT	LT REFINISH			2.5	4
I	0104		FENDER, FRONT	RT REPAIR			0.5*	1
L	0104		FENDER, FRONT	RT REFINISH			2.5	4
I	0389	02	PANEL, QUARTER	LT REPAIR			1.5*	1

193

L	0389	PANEL, QUARTER	LT REFINISH		2.8 4
L	M14	CORROSION PROTECTION	REFINISH	12.50*	0.4*1*
L	M15	COLOR TINT	REFINISH	*	0.5*1*
L	M17	COVER CAR EXTERIOR	REFINISH	10.00*	*4*
I	M60	HAZARD. WSTE. REM.	SUBLET REPAIR	4.00*	*1*

17 ITEMS

MC MESSAGE(S)

02 PART NO. DISCONTINUED, CALL DEALER FOR EXACT PART NO

09 INCLUDES 0.6 HOURS MAJOR PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

OTHER PARTS				22.50
PAINT MATERIAL				330.00
PARTS TOTAL				352.50
TAX ON PARTS & MATERIAL @			7.250%	25.56
LABOR	RATE	REPLACE HRS	REPAIR HRS	
1-SHEET METAL	32.00	1.5	7.8	297.60
2-MECH/ELEC	55.00			
3-FRAME	36.00			
4-REFINISH	32.00	15.0		480.00
5-PAINT MATERIAL	22.00			
LABOR TOTAL				777.60
TAX ON LABOR		@	0.000%	
SUBLET REPAIRS				4.00
TOWING				
STORAGE				

GROSS TOTAL 1,159.66

NET TOTAL 1,159.66

ADP SHOPLINK U5093 ES CD LOG 894-1 DATE 10/20/99 01:35:12PM R6.1 CD 10/99

PXN:N/00/00/00/00 CUM:/// HOST LOG

COPYRIGHT 1999, AUTOMATIC DATA PROCESSING, INC.

3.0 HOURS WERE ADDED TO THIS ESTIMATE BASED ON ADP'S TWO-STAGE REFINISH
FORMULA: 20% OF REFINISH HOURS, AFTER OVERLAP, PLUS 0.6 HOURS FOR THE FIRST
MAJOR PANEL, WHERE NOTED.

THANK YOU AND HAVE A NICE DAY*****REPAIR TIME 4 DAYS. THIS IS A VISUAL
APPRAISAL ONLY.....DAVID COLLISION REPAIR INC. HEREBY WARRANTS ALL BODY AND
PAINT WORK COVERED ON THE DESIGNATED REPAIR ORDER AGAINST ANY DEFECTS IN
MATERIAL AND WORKMANSHIP FOR AS LONG AS YOU OWN THE VEHICLE. PARTS ARE
COVERED BY MANUFACTURE WARRANTY.

12:30 pm Oct. 19, 99

Ricardo Salay and I, were hauling Brush from Saramada subdivision to the faculty. We had one chain on the stock pile to keep it secured.

A limb blew off the trailer and landed in the middle of the road between Williams Drive and Highway #29.

Ricardo was assisting another party; he told me to go and get the limb off of the road. I was in the process of getting the limb out of the road. Directly ahead a couple in a Pontiac Granam two door car hit the limb. Bratched and chipped the paint, that was all I could see that was harmed. The person driving the Gran am was L.V. Reese, Jr.

Chris Shofner
Chris Shofner

RECORDERS MEMORANDUM
All or parts of the text on this page was not
clearly legible for satisfactory recordation.